

Inspection Photos

1/17/2019

Operator: BAYHORSE PETROLEUM LLC - 10234

Location ID: 429611

Inspection Doc. Number: 682504438

Kiowa County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: BAYHORSE PETROLEUM LLC - 10234
Location ID: 429611



Photo 1: 2015 google earth aerial image. Photo shows area of disturbance mapped on the ground with a GPS by inspector. Mapped disturbance ~2.36 acres.



Photo 2: Photo taken from the south end of the location, facing north. Photo shows vegetation over the reclamation area. Location remains predominantly bare and exposed soil, or vegetated by undesirable weedy plant species such as Russian thistle.



Photo 3: Photo taken from the northwest end of the location, facing east. See comments under photo 2



Photo 4: Photo taken from the northwest end of the location, facing south. See comments under photo 2



Photo 5: Photo taken from the west end of the location, facing northeast. See comments under photo 2



Photo 6: Photo taken from the west end of the location, facing south. See comments under photo 2. Photo also shows fill slopes.



Photo 7: Photo taken from the east end of the location, facing west. See comments under photo 2



Photo 8: Photo taken from the east end of the location, facing north. See comments under photo 2



Photo 9: Photo taken from the northeast end of the location, facing south. See comments under photo 2



Photo 10: Photo taken from the southeast end of the location, facing north. See comments under photo 2



Photo 11: Photo taken from the southeast end of the location, facing northwest. See comments under photo 2



Photo 12: Photo taken from the south end of the location, facing southeast. Photo shows access road. See comments under photo 2.



Photo 13: Photo taken from the southwest end of the location, facing northwest. See comments under photo 2



Photo 14: Photo taken from the west end of the location, facing east. See comments under photo 2



Photo 15: Photo taken from the adjacent reference area. Vegetation observed included Blue grama, Sand Sage, Sand Dropseed, Western Wheatgrass etc... Photo shows location is not reflective of the reference areas.