

Inspection Photos

1/17/2019

Operator: BAYHORSE PETROLEUM LLC - 10234

Location ID: 440889

Inspection Doc. Number: 682504443

Kiowa County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: 2015 google earth aerial image. Photo shows area of the location where vegetation is not progressing towards reclamation requirements. Disturbance ~4.3 acres in size.



Photo 2: Photo taken from the access road on the north end of the location, facing south. Photo shows road remains predominantly bare and exposed soil. Desirable vegetative establishment does not appear to be progressing towards reclamation standards.



Photo 3: Photo taken from the west end of the location , facing north. Photo shows location remains predominantly bare and exposed soil. Desirable vegetative establishment does not appear to be progressing towards reclamation standards.



Photo 4: Photo taken from the west end of the location, facing northeast. Photo shows location remains predominantly bare and exposed soil. See comments under photo 4.



Photo 5: Photo taken from the west end of the location, facing southeast. Photo shows location remains predominantly bare and exposed soil. See comments under photo 4.



Photo 6: Photo taken from the west end of the location, facing nsouth. Photo shows location remains predominantly bare and exposed soil. See comments under photo 4.