

Laramie Energy LLC  
Api # 05-077-09162  
Inspection # 6775001805



photo from entrance of pad

Laramie Energy LLC  
Api # 05-077-09162  
Inspection # 6775001805



Wellhead sign or signs missing

Laramie Energy LLC  
Api # 05-077-09162  
Inspection # 6775001805



Tank Battery

Laramie Energy LLC  
Api # 05-077-09162  
Inspection # 6775001805



Unused equipment stored on location