

Inspection Photos
Location Name: Warren McMillan Pit
Facility ID:118641



Photo 1 – 1999 Google Earth aerial imagery. Unable to precisely determine location of permitted Pit #118641.



Photo 2 – Recently removed fiberglass partially buried tank location.

Inspection Photos
Location Name: Warren McMillan Pit
Facility ID:



Photo 1 – North of battery facing south, no surface indication of a pit.



Photo 2 – At battery facing north, no surface indication of a pit.