

Inspection Photos
Location Name: WRD UNIT 29-33
Location ID: 05-103-09920
Inspection: 679702752



Photo 1. Location looking south.



Photo 2. Meter building and separator.

Inspection Photos
Location Name: WRD UNIT 29-33
Location ID: 05-103-09920
Inspection: 679702752



Photo 3. Producing well battery.



Photo 4. Emission control devices, pump jack, and injection well battery.

Inspection Photos
Location Name: WRD UNIT 29-33
Location ID: 05-103-09920
Inspection: 679702752



Photo 5. Injection well battery.



Inspection Photos
Location Name: WRD UNIT 29-33
Location ID: 05-103-09920
Inspection: 679702752



Photo 6. Strong hydrocarbon odor near tank.



Photo 7. Strong hydrocarbon odor near tank.