

Inspection Photos
Location Name: WRD DOW 20-22
Location ID: 05-103-09894
Inspection: 679702765



Photo 1. Location looking east.



Photo 2. Bird protection not visible on oil tank stack.