



Lease Sign for Context
Pictures Takes 2019-01-26



Stained Soil at Wellhead Was Removed and Berm Was Built Around Wellhead

Picture Looking West Showing South Berm Was Cleaned and BMP's
Added For Erosion Control



Picture Looking North Showing Stained Soil Was Placed On South Side Of Pit For Biodegradation and Tilling. BMP's Were Used For Erosion Control

