

Inspection Photos

Loc#335309

Operator: Terra

Inspection Number: 692400583

Inspection Date: 1/21/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

January 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Bonneville Loc#335309



Photo#2:

Location appears well maintained and Vegetation in Interim Reclamation areas is well established.

January 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Bonneville Loc#335309