

Construction and Storm Water Inspection

January 10, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC – 10633

Location ID: 451044

Inspection Document #: 674902408

Weld County, CO

NWNE Section 19 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 1. Photo taken from the entrance of the location off CR 20.5, facing South. Operator has started topsoil salvage operations along the access road. At the time of this inspection, no stormwater erosion issues were observed at location or along the access road.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Google Earth aerial imagery showing the approximate access road in red off CR 20.5 . See comments from Photo 1.