

Construction and Storm Water Inspection

January 15, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC – 10633

Location ID: 451044

Inspection Document #: 674902496

Weld County, CO

NWNE Section 19 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 1. Photo taken from the access road, facing North. Photo depicts the access road under construction.



Photo 2. Photo taken from the access road, facing West. See comments from Photo 1.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 3. Photo taken from the northeastern perimeter of the location, facing West. See comments from Photo 1.



Photo 4. Photo taken from the northeastern perimeter of the location, facing South. Photo illustrates the ditch and berm BMP that has been installed around the perimeter of the location.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 5. Photo taken from the northern perimeter of the location, facing West. Photo illustrates the topsoil salvage operations underway and has been temporarily stabilized with equipment tracking.



Photo 6. Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 4.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 7. Photo taken from the southern perimeter of the location, facing South. See comments from Photo 5.



Photo 8. Photo taken from the southern perimeter of the location, facing Northwest. See comments from Photo 5.