

# Construction and Storm Water Inspection

January 21, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC – 10633

Location ID: 451044

Inspection Document #: 674902498

Weld County, CO

NWNE Section 19 T2N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



**Photo 1.** Photo taken from the entrance of the location off CR 205, facing North. Operator has installed gravel potentially to limit tracking onto the county road. BMPs in proper functioning condition at the time of this inspection.



**Photo 2.** Photo taken from the entrance of the location off CR 20.5, facing South. See comments from Photo 1.