

Final Reclamation and Stormwater Inspection

January 23, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 336117

Inspection Document #: 674902474

Weld County, CO

SESE Section 36 T3N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /3N66W36
Location ID: 336117



Photo 1. Photo taken from the location, facing East. Appears the Operator has removed all well equipment from the P&A well on the Active Location.



Photo 2. Photo taken from the well location, facing Southeast. See comments from Photo 1.