

Inspection Photos

Location Name: COLTRANE-IGO-65N66W /28SENW

Location #: 323060



Photo #1

Coltrane-Igo # 1 (05-123-12504) wellsite

Shut-In | LOTO

No Orange SI / TA tag per agreement



Photo #2

Coltrane-Igo # 1, Igo 28-3H6 Battery

Shut-down

Contents / Capacity not posted on crude oil tank



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources