

Inspection Photos
Location Name: IGO-65N66W /28NENW
Location #: 330085



Photo #1
Igo 28-3H6 (05-123-18373) wellsite
Shut-In | LOTO
Weeds appear to be mitigated
No Orange SI / TA tag per agreement



Photo #2
Coltrane-Igo # 1, Igo 28-3H6 Battery
Shut-down
Contents / Capacity not posted on crude oil tank