

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2019

Submitted Date:

01/28/2019

Document Number:

679600269**FIELD INSPECTION FORM**Loc ID 327218 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                  | Comment         |
|--------------|-------|--|-----------------|
| Kraich, Adam |       | adam.kraich@state.co.us                |                 |
| ,            |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM | ALL INSPECTIONS |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 246531      | WELL | SI     | 09/01/2017  | GW         | 123-14328 | SPOMER-BC J 33-13 | AL          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |       |       |  |
|--------------------|-------|-------|--|
| Type               | OTHER |       |  |
| Comment:           | None  |       |  |
| Corrective Action: |       | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Equipment:**

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| Type: Plunger Lift                | # 0 |       | corrective date |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 0 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Gas Meter Run               | # 0 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------|---------|--------|
| PRODUCED WATER     | 0 |          |      |         | ,      |
| Comment:           |   |          |      |         |        |
| Corrective Action: |   | Date:    |      |         |        |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type     | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|----------|---------------------|---------------------|-------------|
|          |          |                     |                     |             |
| Comment: |          |                     |                     |             |

|                    |          |                     |                     |             |        |  |
|--------------------|----------|---------------------|---------------------|-------------|--------|--|
| Corrective Action: |          |                     |                     |             | Date:  |  |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS |  |
| CRUDE OIL          | 0        |                     |                     |             | ,      |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |
| <b>Paint</b>       |          |                     |                     |             |        |  |
| Condition          |          |                     |                     |             |        |  |
| Other (Content)    |          |                     |                     |             |        |  |
| Other (Capacity)   |          |                     |                     |             |        |  |
| Other (Type)       |          |                     |                     |             |        |  |
| <b>Berms</b>       |          |                     |                     |             |        |  |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |  |
|                    |          |                     |                     |             |        |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |
| <b>Venting:</b>    |          |                     |                     |             |        |  |
| Yes/No             |          |                     |                     |             |        |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |
| <b>Flaring:</b>    |          |                     |                     |             |        |  |
| Type               |          |                     |                     |             |        |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |

**Inspected Facilities**Facility ID: 246531 Type: WELL API Number: 123-14328 Status: SI Insp. Status: AL**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: In regards to Form 6 Doc# 401874587 (in process). Site is free and clear of all equipment. See attached photo.

Corrective Action: 

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 679600270    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4717216">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4717216</a> |