

Inspection Photos

ALs Loc#422286

Operator: Ursa

Inspection Number: 692400588

Inspection Date: 1/21/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location Well Corral.

January 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa ALs Loc#422286



Photo#2:
View of three AL Well positions with signs installed.

January 21, 2019