

Inspection Photos

Location Name: COLTRANE-PM-65N66W /28SWNW

Location #: 327000




Photo #1

Coltrane-PM J28-5 (05-123-13989) wellsite

MIT - Delinquent



Photo #2

Coltrane-PM J 28-4, 28-5

Igo Farms J 28-19D, 28-20D, 28-31D, 28-32D

Battery – Oil tanks



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: COLTRANE-PM J-65N66W /28NWNW

Location #: 326999



Photo #3

Coltrane-PM J 28-4, 28-5

Igo Farms J 28-19D, 28-20D, 28-31D, 28-32D

Battery – Separators | ECDs

