

Inspection Photos

1/28/2019

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 460931

Inspection Doc. Number: 682504453

Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the southwest end of the location, facing north. Photo shows topsoil salvage and pad construction in process. Photo also shows operator has installed surface roughening along the perimeter of the location.



Photo 2: Photo taken from the southwest end of the location, facing east Photo shows topsoil salvage and pad construction in process. Photo also shows operator has installed surface roughening along the perimeter of the location.

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 460931



Photo 3: Photo taken from the southeast end of the location, facing northwest. Photo shows topsoil salvage and pad construction in process. Photo also shows operator has installed surface roughening along the perimeter of the location.



Photo 4: Photo taken from the south end of the location, facing south. Photo of topsoil salvage in process.