

# *Inspection Photos*

*Loc#422286*

*Operator: Ursa*

*Inspection Number: 692400589*

*Inspection Date: 1/21/2019*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to Northwest.

January 21, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa Monument Ridge Loc#422286



Photo#2:  
One Anchor, Marker down.

January 21, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa Monument Ridge Loc#422286





Photo#3:

Interim Reclamation area on backside of South berm; insert is close up of Weedy species.

January 21, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa Monument Ridge Loc#422286