

Inspection Photos  
Location Name: UPRC Federal 23-1  
Location ID: 330502



Photo 1: Battery sign with incorrect operator.



Photo 2: Tank Battery. Pictured to left, tank does not have correct labeling.

Inspection Photos  
Location Name: UPRC Federal 23-1  
Location ID: 330502



Photo 3: Trash inside heater treater along the south and east wall.



Photo 4: Pump jack with incorrect signage.

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**Location ID: 330502**



Colorado Oil & Gas Conservation Commission  
40°49'34", -104°31'19", 1567.2m, 33°  
01/29/2019 12:34:10 PM

**Photo 5: Produced water tank**



Colorado Oil & Gas Conservation Commission  
40°49'34", -104°31'18", 1566.5m, 323°  
01/29/2019 01:14:11 PM

**Photo 6: Pit to produced water tank.**