

Inspection Photos

Location Name: MOSSBERG J-65N66W /30SESE

Location #: 310537



Photo #1

Mossberg J 30-23 (05-123-26554) wellsite

Temporarily Abandoned | TA

Emergency contact number NOT accurate



Photo #2

Mossberg J 30-23 – Battery site

Abandoned

All Equipment has been removed

