

Inspected Facilities

Facility ID: 290742 Type: WELL API Number: 071-09291 Status: PR Insp. Status: PR

COGCC Comments

Comment	User	Date
<p>Followup inspection to inspection doc 687903091 in response to FIRR doc 687903091. Based on photos submitted by operator corrective actions have been completed. (photos attacked to FIRR)</p>	<p>beardsit</p>	<p>01/30/2019</p>