

Inspection Photos
Location Name: Hosmer #43-32
Location ID: 320289




Photo 1 WH



Photo 2 TNK BTRY



Inspection Photos
Location Name: Hosmer #43-32
Location ID: 320289



Photo 3 Unused equipment ties PU parts and fence in disrepair



Photo 4 Unused equipment guard and tubing

Inspection Photos
Location Name: Hosmer #43-32
Location ID: 320289



Photo 5 ECD, sep and meter run

