

Interim Reclamation and Stormwater Inspection

January 28, 2019

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 424712

Inspection Document #: 682404470

Weld County, CO

NWNW Section 17 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Slick Rock /17-11-7-60

Location ID: 424712



Photo 1. Photo taken from the entrance of the location, facing East. Photo illustrates the northern well pad. Operator has failed to perform interim reclamation.



Photo 2. Photo taken from the entrance of the location, facing South. See comments under Photo 1.

Inspection Photos

Location Name: Slick Rock /17-11-7-60

Location ID: 424712



Photo 3. Photo taken from the western well pad, facing South. Photo illustrates unmanaged weeds along the fill slope. Operator shall control weeds and weed debris per Rule 603.f.



Photo 4. Photo taken from the southwestern well pad, facing South. Photo illustrates unmanaged weeds along the fill slope and weed debris along the perimeter fence.

Inspection Photos

Location Name: Slick Rock /17-11-7-60

Location ID: 424712



Photo 5. Photo taken from the southwestern well pad, facing East. See comments under Photo 3.



Photo 6. Photo taken from the southwestern well pad, facing South. See comments under Photo 3.

Inspection Photos

Location Name: Slick Rock /17-11-7-60

Location ID: 424712



Photo 7. Photo taken from the southern well pad, facing West. See comments under Photo 1.



Photo 8. Photo taken from the southern well pad, facing East. See comments under Photo 1.

Inspection Photos

Location Name: Slick Rock /17-11-7-60

Location ID: 424712



Photo 9. Photo taken from the eastern well pad, facing North. See comments under Photo 3.



Photo 10. Photo taken from the topsoil stockpile located along the northeastern location, facing South. Photo illustrates unmanaged weeds along the eastern slope of the topsoil stockpile.

Inspection Photos

Location Name: Slick Rock /17-11-7-60

Location ID: 424712



Photo 11. Photo taken from the topsoil stockpile located along the northeastern location, facing South. Photo illustrates unmanaged weeds along the western slope of the topsoil stockpile.



Photo 12. Photo taken from the northern well pad, facing West. See comments under Photo 3.