

# Interim Reclamation and Stormwater Inspection

January 28, 2019

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 428592

Inspection Document #: 682404472

Weld County, CO

NENE Section 8 T7N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Pergamos /8-41-7-60  
Location ID: 428592



**Photo 1.** Photo taken from the entrance of the location, facing East. Photo illustrates the northern well pad. Operator has failed to perform interim reclamation.



**Photo 2.** Photo taken from the entrance of the location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: Pergamos /8-41-7-60  
Location ID: 428592



**Photo 3.** Photo taken from the eastern well pad, facing South. Photo illustrates unmanaged weeds along the fill slope. Operator shall control weeds and weed debris per Rule 603.f.



**Photo 4.** Photo taken from the southern well pad, facing West. See comments under Photo 1.