

Inspection Photos
Location Name: SCHANK-65N66W /35SWNE
Location #: 323018



Photo #1
Schank #1 (05-123-12444) wellsite
Temporarily Abandoned | TA

Inspection Photos
Location Name: SCHANK-65N66W /35SWNE
Location #: 323018



Colorado Oil & Gas Conservation Commission
40.36049, -104.74543, 1405.0m, 157°
2019/01/31 09:34:09 AM

Photo #2
Schank #1, J 35-2 Battery site
Abandoned
Unused Equipment



Colorado Oil & Gas Conservation Commission
40.36004, -104.74553, 1411.0m, 125°
2019/01/31 09:31:09 AM

Photo #3
Schank #1, J 35-2 Battery site
Abandoned
Unused Equipment
Gas meter run, line pipe, automation controls