

Final Reclamation and Stormwater Inspection

January 29, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC – 10110

Location ID: 319776

Inspection Document #: 674902514

Weld County, CO

NENE Section 36 T1S R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY/1S65W10

Location ID: 319776



Photo 1. Photo taken from the access road looking into the location, facing West. Operator has performed reclamation activities. However, the location lacks uniform perennial vegetation and are covered in weedy, annual vegetation which includes but not limited to cheatgrass and kochia. The access road remains.



Photo 2. Photo taken from the access road looking into the location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY/1S65W10

Location ID: 319776



Photo 3. Photo taken from the location, facing South. See comments from Photo 1. The pipe riser and fence have been removed. However, the location is barren with no vegetation.



Photo 4. Photo taken from the well location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY/1S65W10

Location ID: 319776



Photo 5. Photo taken from the location. Concrete Debris left on location.



Photo 6. Photo taken from the location, facing Northwest. See comments from Photo 1.