

Location Name: White AL-1 API: 017-06660 Inspection Date: 1/31/2019



Emergency contact number is not in service.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: White AL-1 API: 017-06660 Inspection Date: 1/31/2019



Jan 31, 2019 11:35:12
38.81827N 102.05985W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: White AL-1 API: 017-06660 Inspection Date: 1/31/2019



Stained soil around wellhead.



Location Name: White AL-1 API: 017-06660 Inspection Date: 1/31/2019



Jan 31, 2019 11:35:29
38.81825N 102.05986W

I observed a steady, forceful stream of gas being vented from this valve and a 4 gas meter detected methane gas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: White AL-1 API: 017-06660 Inspection Date: 1/31/2019

