

Antelope O-20 Available Water Sources

Receipt	Permit	Well Status	Landowner/ Contact Name	Primary Use	Original permit holder	Comments
0016005	16005-MH	Permit Issued	70 RANCH LLC	NATIONAL HOG FARMS	Monitoring/ Sampling	Monitoring Well
0018127	18127-MH	Well Constructed	70 RANCH LLC	NATIONAL HOG FARM	Monitoring/ Sampling	Monitoring Well
0023005	23005-MH	Well Abandoned	70 RANCH LLC	NATIONAL HOG FARM	Monitoring/ Sampling	Monitoring Well / Abandoned
0023006	23006-MH	Well Abandoned	70 RANCH LLC	NATIONAL HOG FARM	Monitoring/ Sampling	Monitoring Well / Abandoned
0023007	23007-MH	Well Abandoned	70 RANCH LLC	NATIONAL HOG FARM	Monitoring/ Sampling	Monitoring Well / Abandoned
0311531E	36657-M	Well Abandoned	70 RANCH LLC	NATIONAL HOG FARMS	Monitoring/ Sampling	Monitoring Well / Abandoned
0314638K	40921-M	Well Abandoned	70 RANCH LLC	NATIONAL HOG FARMS INC	Monitoring/ Sampling	Monitoring Well / Abandoned
0336034H	163753-	Well Abandoned	70 RANCH LLC	NATIONAL HOG FARMS INC	Monitoring/ Sampling	Monitoring Well / Abandoned
0336034I	163754-	Well Abandoned	70 RANCH LLC	NATIONAL HOG FARMS INC	Monitoring/ Sampling	Monitoring Well / Abandoned
0385493F	188374-	Well Constructed	70 RANCH LLC	NATIONAL HOG FARMS	Monitoring/ Sampling	Monitoring Well
3663275F		Application Information Requested	70 RANCH LLC	70 RANCH RESOURCES DEVELOPMENT LLC	Industrial, Irrigation	Not constructed
3663275I		Application Information Requested	70 RANCH LLC	70 RANCH RESOURCES DEVELOPMENT LLC	Industrial, Irrigation	Not constructed
9065627	81437-	Well Constructed	70 RANCH LLC	ALLARD CATTLE COMPANY	Stock	Unable to collect representative sample from well - broken sampling port