

Inspection Photos

1/31/2019

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 425596

Inspection Doc. Number: 682504457

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: VERDAD RESOURCES LLC - 10651
Location ID: 425596



Photo 1: Photo taken from the north end of the location facing west. Photos 1-5 provide an overview of the location (interim and production areas) from west, southwest, southeast, to east.

Inspection Photos
Operator: VERDAD RESOURCES LLC - 10651
Location ID: 425596



Photo 2:

Inspection Photos
Operator: VERDAD RESOURCES LLC - 10651
Location ID: 425596



Photo 3:

Inspection Photos
Operator: VERDAD RESOURCES LLC - 10651
Location ID: 425596



Photo 4:

Inspection Photos
Operator: VERDAD RESOURCES LLC - 10651
Location ID: 425596



Photo 5:



Photo 6: Photo taken from the northwestern area of the location, facing south. Photo shows area where freshwater pit existed. Pit appears to have been closed. Photo shows interim reclamation in process.



Photo 7: Photo taken from the interim areas on the west end of the location, facing west. Desirable perennial germination evident, however interim areas predominantly undesirable weedy plant species such as Russian thistle.