

# Inspection Photos

1/31/2019

Operator: VERDAD RESOURCES LLC - 10651


Location ID: 429096

Inspection Doc. Number: 682504469

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: VERDAD RESOURCES LLC - 10651  
Location ID: 429096



**Photo 1:** 2013 Google earth aerial imagery. Photo shows disturbance area for the location. A disturbance area of 5.27 acres was measured using a Trimble Juno 3B handheld device. This exceeds the permitted disturbance area of 4.1 acres.

Inspection Photos  
Operator: VERDAD RESOURCES LLC - 10651  
Location ID: 429096



**Photo 2:** Photo taken from the east end of the location, facing south. Photos 2-5 provides an overview of the location from south, southwest, northwest to north. Photos also show interim reclamation has not been conducted in accordance with COGCC rule 1003.

Inspection Photos  
Operator: VERDAD RESOURCES LLC - 10651  
Location ID: 429096



**Photo 3:** See comments under photo 2.

Inspection Photos  
Operator: VERDAD RESOURCES LLC - 10651  
Location ID: 429096



**Photo 4:** See comments under photo 2.



**Photo 5:** See comments under photo 2



**Photo 6:** Photo taken from the west end of the location, facing east. Photo shows interim reclamation has not been conducted in accordance with COGCC rule 1003. Blue line shows pad perimeter.



**Photo 7:** Photo taken from the west end of the location, facing east. Photo shows interim reclamation has not been conducted in accordance with COGCC rule 1003. Blue line shows pad perimeter.