

# Inspection Photos

1/31/2019


Operator: VERDAD RESOURCES LLC - 10651

Location ID: 425439

Inspection Doc. Number: 682504473

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** 2013 Google earth aerial imagery. Photo shows disturbance area for the location. A disturbance area of 7.2 acres was measured using a Trimble Juno 3B handheld device. This exceeds the permitted disturbance area of 6.6 acres.





**Photo 2:** Photo taken from the nsoutheast end of the pad, facing west. Photos 2-5 provides and overview of the location from west, northwest to north. Photos also show interim reclamation has not been conducted in accordance with COGCC rule 1003.



Inspection Photos  
Operator: VERDAD RESOURCES LLC - 10651  
Location ID: 425439



**Photo 3:** See comments under photo 2.





**Photo 4:** See comments under photo 2.





**Photo 5:** Photo taken from the south end of the pit #431610, facing northeast. Location received an approved 502.b variance to delay interim reclamation of the location for three (3) years until 12/03/2018. Photos shows pit has not been closed/reclaimed.





**Photo 6:** Photo taken from the soil stockpile on the west end of the location, facing north. Photo shows stormwater erosion degradation along slopes of soil stockpile.