

Location Name: Arapahoe Unit 173    API: 017-06838    Inspection Date: 1/31/2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Arapahoe Unit 173    API: 017-06838    Inspection Date: 1/31/2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Arapahoe Unit 173    API: 017-06838    Inspection Date: 1/31/2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Arapahoe Unit 173    API: 017-06838    Inspection Date: 1/31/2019



Jan 31, 2019 12:24:54  
38.84600N 102.12083W

6 by 5 foot oil spill.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Arapahoe Unit 173    API: 017-06838    Inspection Date: 1/31/2019



Jan 31, 2019 12:25:27  
38.84599N 102.12081W

6 by 5 foot oil spill.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Arapahoe Unit 173    API: 017-06838    Inspection Date: 1/31/2019



Stained soil around wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Arapahoe Unit 173    API: 017-06838    Inspection Date: 1/31/2019



Stained soil around wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Arapahoe Unit 173    API: 017-06838    Inspection Date: 1/31/2019



Crude oil spill



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources