

Inspection Photos
Location Name: CONTINENTAL 7-22
Location ID: 05-103-08400
Inspection: 679702856



Photo 1. Location looking northwest.



Photo 2. Well head.

Inspection Photos

Location Name: CONTINENTAL 7-22

Location ID: 05-103-08400

Inspection: 679702856



Photo 3. Blow down tank without a label.



Riser next to tank not capped.