

**Inspection Photo (s)**  
**GGU Jolley 13D**  
**API # 05-045-16357**  
**Inspection # 689303132**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo (s)**  
**GGU Jolley 13D**  
**API # 05-045-16357**  
**Inspection # 689303132**



**Location Photo #3, Stained ground under scrubber pot.**



**Location Photo #4, Stained ground under scrubber spot.**