

Inspected Facilities

Facility ID: 240958 Type: WELL API Number: 123-08746 Status: PR Insp. Status: PR

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| Follow up inspection to Doc# 688400286 in resoponse to FIRR #688400286. Based on photos submitted be operator corrective actions have been completed. (photos attached to FIRR) | silverr | 02/01/2019 |