



**Inspected Facilities**

Facility ID: 203558 Type: WELL API Number: 001-09118 Status: SI Insp. Status: SI

**COGCC Comments**

Comment	User	Date
Follow up inspection to Doc# 688400405 in response to FIRR #401808877. Based on photos submitted by operator corrective actions have been completed. (photos attached to FIRR)	silverr	02/04/2019