

Inspected Facilities

Facility ID: 203449 Type: WELL API Number: 001-09008 Status: SI Insp. Status: SI

COGCC Comments

Comment	User	Date
Follow up inspection to Doc# 688400407 in response to FIRR #688400407. Based on photos submitted by operator corrective actions have been completed. (photos attached to FIRR)	silverr	02/04/2019