

Final Reclamation and Stormwater Inspection

January 29, 2019

Operator: EXTRACTION OIL & GAS INC – 10459

Location ID: 320086

Inspection Document #: 674902515

Weld County, CO

SWNE Section 9 T1S R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EXTRACTION OIL & GAS/1S65W9
Location ID: 320086



Photo 1. Photo taken from the access road of CR , facing South. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch.



Photo 2. Photo taken from the access road, facing South. See comments from Photo 1.

Inspection Photos
Location Name: EXTRACTION OIL & GAS/1S65W9
Location ID: 320086



Photo 3. Photo taken from the access road looking into the location, facing West. Appears the Operator has fenced in the location. See comments from Photo 1.



Photo 4. Photo taken from the well location, facing North. See comments from Photo 1. Photo depicts equipment still on location.

Inspection Photos
Location Name: EXTRACTION OIL & GAS/1S65W9
Location ID: 320086



Photo 5. Photo taken from the location, facing East. See comments from Photo 1.



Photo 6. Photo taken from the access road, facing North. See comments from Photo 1.