

# Final Reclamation and Stormwater Inspection

January 29, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 327317

Inspection Document #: 674902517

Weld County, CO

SWSW Section 35 T1N R65W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /1N65W35  
Location ID: 327317



**Photo 1.** Photo taken from the access road looking into the location, facing East. Operator has performed final reclamation activities. However, the access road and location lacks uniform perennial vegetation and are covered in weedy, annual vegetation which includes but not limited to Russian thistle, kochia, and cheatgrass.



**Photo 2.** Photo taken from the access road, facing East. See comments from Photo 1.



Inspection Photos  
Location Name: KERR MCGEE /1N65W35  
Location ID: 327317



**Photo 3.** Photo taken from the access road. See comments from Photo 1.



**Photo 4.** Photo taken from the well location, facing East. See comments from Photo 1.



Inspection Photos  
Location Name: KERR MCGEE /1N65W35  
Location ID: 327317



**Photo 5.** Photo taken from the access road looking into the location, facing Southeast. See comments from Photo 1.



**Photo 6.** Photo taken from the location, facing Southeast. See comments from Photo 1.

Inspection Photos  
Location Name: KERR MCGEE /1N65W35  
Location ID: 327317



**Photo 7.** Photo taken from the reference location, facing North. Note the uniform perennial grass cover.



**Photo 8.** Photo taken from the reference location, facing East. See comments from Photo 5.



Inspection Photos  
Location Name: KERR MCGEE /1N65W35  
Location ID: 327317



**Photo 9.** Photo taken from the reference location, facing South. See comments from Photo 5.



**Photo 10.** Photo taken from the reference location, facing West. See comments from Photo 5.