

Final Reclamation and Stormwater Inspection

January 29, 2019

Operator: EXTRACTION OIL & GAS INC – 10459

Location ID: 320101

Inspection Document #: 674902522

Weld County, CO

SWSW Section 2 T1S R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: EXTRACTION OIL & GAS/1S65W2
Location ID: 320101



Photo 1. Photo taken from the access road, facing South. Operator has performed final reclamation activities. However, the access road and facility lacks uniform perennial vegetation and are covered in weedy, annual vegetation which includes but not limited to cheatgrass and scotch thistle.



Photo 2. Photo taken from the well location, facing North. See comments from Photo 1.

Inspection Photos
Location Name: EXTRACTION OIL & GAS/1S65W2
Location ID: 320101



Photo 3. Photo taken from the access road, facing Southwest. See comments from Photo 1.



Photo 4. Photo taken from the access road, facing West. See comments from Photo 1.

Inspection Photos
Location Name: EXTRACTION OIL & GAS/1S65W2
Location ID: 320101



Photo 5. Photo taken from the facility location. See comments from Photo 1.



Photo 6. Photo taken from the access road, facing North. See comments from Photo 1.