

Inspection Photos

Location Name: LUNDVALL-65N66W /18NESW

Location #: 332893



Photo #1

Lundvall 1 (05-123-10500) Wellsite
No Emergency contact number posted
from prev. FIR



01-31-2019

Photo #2

Lundvall 1 Wellsite
Emergency contact number posted
FIRR Operator provided photo



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LUNDVALL-65N66W /18NESW

Location #: 332893



Photo #3

Lundvall 18-6 (05-123-22966) Wellsite
No Emergency contact number posted
from prev. FIR



Photo #4

Lundvall 18-6 Wellsite
Emergency contact number posted
FIRR Operator provided photo



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LUNDVALL-65N66W /18NESW

Location #: 332893



Photo #5

Lundvall 18-12 (05-123-22962) Wellsite
No Emergency contact number posted
from prev. FIR



Photo #6

Lundvall 18-12 (05-123-22962) Wellsite
Emergency contact number posted
FIRR Operator provided photo



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LUNDVALL-65N66W /18NESW

Location #: 332893



Photo #7

Lundvall 1, 18-6, 18-12 Battery

from prev. FIR



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources