



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Nov 1, 2018 11:19:28 AM MDT
Server Receive Date:	Nov 1, 2018 11:20:08 AM MDT
Reference Number:	20181101-1890954574
Location:	10495 Co Rd 213, Durango, CO 81303, USA Nov 1, 2018 11:19:52 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	reclamationtablet
Date	Oct 30, 2018
Well Name	LUCHINI GAS UNIT 32-6-11 2
API Number	50070622100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Seeding Erosion Repairs Install Rock Run Down

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

installed 3 rock rundowns where rills were forming  
and seeded/hydromulched around the well pad.