

Final Reclamation and Stormwater Inspection

January 29, 2019

Operator: VERDAD OIL & GAS CORPORATION – 10485

Location ID: 441850

Inspection Document #: 674902518

Weld County, CO

NWNE Section 26 T1N R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: VERDAD OIL & GAS/1N65W26

Location ID: 441850



Photo 1. Photo taken from the location, facing East. This is an abandoned location that appears to have a pad built on the location.



Photo 2. Photo taken from the well location, facing Northeast. See comments from Photo 1.

Inspection Photos

Location Name: VERDAD OIL & GAS/1N65W26

Location ID: 441850



Photo 3. Photo taken from the location, facing West. See comments from Photo 1.



Photo 4. Photo taken from the well location, facing South. See comments from Photo 1.