

Inspection Photos
Location Name: LAW-67N66W /17NESW
Location #: 319375



Photo #3
Law 1-17 Wellsite
Stained soil & fluids on wellhead
from prev. FIR



Photo #4
Law 1-17 Wellsite
Stained soil & fluids on wellhead

Inspection Photos

Location Name: LAW-67N66W /17NESW

Location #: 319375



Photo #5

Law 1-17 Battery

H2O tank placards – NOT Legible

