

# Final Reclamation Inspection

February 5, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 327954

Inspection Document #: 682404491

Weld County, CO

NENW Section 14 T5N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MYERS #14-21  
Location ID: 327954



Google Earth aerial imagery taken September 7, 2016 during active operations illustrating the well location (red circle) and production facility.

Inspection Photos  
Location Name: MYERS #14-21  
Location ID: 327954



Google Earth aerial imagery taken September 12, 2018, after plugging and abandonment operations. COGCC Staff conducted a site investigation and determined the Location has not been properly contoured. There were observed low and high spots which are affecting revegetation throughout the Location and flood irrigation operations. Using a Trimble Juno handheld device, Staff mapped the observed areas of concern.



Inspection Photos  
Location Name: MYERS #14-21  
Location ID: 327954



**Photo 1.** Photo taken from Low Spot #1, facing West. The Location has not been properly contoured per Rule 1004. Photo illustrates an observed low spot which is affecting revegetation and flood irrigation operations.



Inspection Photos  
Location Name: MYERS #14-21  
Location ID: 327954



**Photo 2.** Photo taken from Low Spot #2, facing East. Photo illustrates an observed low spot along the irrigation berm. This low spot does not allow the irrigation berm to properly function to control flood irrigated water. Complainant indicated the flood water escapes from this spot not allowing for successful flood irrigation.



Inspection Photos  
Location Name: MYERS #14-21  
Location ID: 327954



**Photo 3.** Photo taken from Low Spot #3, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: MYERS #14-21  
Location ID: 327954



**Photo 4.** Photo taken from the eastern High Spot, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: MYERS #14-21  
Location ID: 327954



**Photo 5.** Photo taken from the central Location, facing West. See comments under Photo 1.



**Photo 6.** Reference photo taken north of the Location, facing West. Photo illustrates vegetation is not reflective of reference area vegetative levels per Rule 1004.