

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/04/2019

Submitted Date:

02/04/2019

Document Number:

695100129

FIELD INSPECTION FORM

Loc ID 319098 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10311
Name of Operator: SRC ENERGY INC
Address: 1675 BROADWAY SUITE 2600
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspections@srcenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242879	WELL	PR	11/01/2017	OW	123-10670	M E DRIER 1	PR
422220	WELL	PR	02/01/2018	OW	123-33193	SRC Pratt 29SD	PR
422221	WELL	PR	10/01/2018	GW	123-33194	SRC Pratt 31-29D	PR
422240	WELL	PR	12/01/2017	OW	123-33205	SRC Pratt 41-29D	PR
422250	WELL	PR	11/01/2017	OW	123-33210	SRC Pratt 42-29D	PR
422255	WELL	PR	11/01/2017	OW	123-33212	SRC Pratt 32-29D	PR
429473	TANK BATTERY	AC	04/14/2009		-	SRC Pratt 41-29D	AC

General Comment:

Inspected Facilities

Facility ID: <u>242879</u>	Type: <u>WELL</u>	API Number: <u>123-10670</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>422220</u>	Type: <u>WELL</u>	API Number: <u>123-33193</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>422221</u>	Type: <u>WELL</u>	API Number: <u>123-33194</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>422240</u>	Type: <u>WELL</u>	API Number: <u>123-33205</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>422250</u>	Type: <u>WELL</u>	API Number: <u>123-33210</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>422255</u>	Type: <u>WELL</u>	API Number: <u>123-33212</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>429473</u>	Type: <u>TANK</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>

COGCC Comments

Comment	User	Date
Followup inspection to inspection doc 691400746 in response to FIRR doc 691400746. Based on photos submitted by operator corrective actions have been completed. (photos attached to FIRR)	beardslt	02/04/2019