

**Inspection Photo (s)**  
**Lazier 23-15B**  
**API # 05-045-11030**  
**Inspection # 689303170**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo (s)**  
**Lazier 23-15B**  
**API # 05-045-11030**  
**Inspection # 689303170**



**Location Photo #3, Unused equipment in  
battery containment.**