

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2019

Submitted Date:

02/06/2019

Document Number:

689303180**FIELD INSPECTION FORM**

Loc ID 335329 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone        | Email                                     | Comment                         |
|----------------|--------------|---|---------------------------------|
| Rider, Lindsay | 970-285-2711 | cogcc.inspections@caerusoila<br>ndgas.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 266558      | WELL | PR     | 07/01/2018  | GW         | 045-09152 | KELL 35-4D (B35NW) | PR          |
| 266568      | WELL | PR     | 02/19/2004  | GW         | 045-09155 | KELL 35-4A (B35NW) | PR          |
| 266572      | WELL | PR     | 09/27/2003  | GW         | 045-09158 | KELL 35-3D (B35NW) | PR          |
| 266573      | WELL | PR     | 02/19/2004  | GW         | 045-09157 | KELL 35-3B (B35NW) | PR          |

**General Comment:**[Routine Field Inspection.](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | DEBRIS |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |
| Type               | TRASH  |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                                 |     |       |                 |
|---------------------------------|-----|-------|-----------------|
|                                 |     |       | corrective date |
| Type: Vertical Heated Separator | # 4 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Plunger Lift              | # 3 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Gas Meter Run             | # 1 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Bird Protectors           | # 1 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Deadman # & Marked        | # 5 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |

**Tanks and Berms:**

|                    |   |          |           |         |        |  |
|--------------------|---|----------|-----------|---------|--------|--|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |  |
| CONDENSATE         | 2 | 300 BBLS | STEEL AST |         | ,      |  |
| Comment:           |   |          |           |         |        |  |
| Corrective Action: |   |          |           |         | Date:  |  |

**Paint**

|                  |               |  |
|------------------|---------------|--|
| Condition        | Adequate      |  |
| Other (Content)  | Methanol tank |  |
| Other (Capacity) | 1000 gallon.  |  |
| Other (Type)     |               |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |                                 |       |      |             |           |         |    |               |    |
|-----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 266558                          | Type: | WELL | API Number: | 045-09152 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
|                       |                                 |       |      |             |           |         |    |               |    |
| Facility ID:          | 266568                          | Type: | WELL | API Number: | 045-09155 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
|                       |                                 |       |      |             |           |         |    |               |    |
| Facility ID:          | 266572                          | Type: | WELL | API Number: | 045-09158 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well producing.                 |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
|                       |                                 |       |      |             |           |         |    |               |    |
| Facility ID:          | 266573                          | Type: | WELL | API Number: | 045-09157 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                | URL   |
|--------------|----------------------------|---|
| 689303181    | Inspection photo 689303181 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4726601">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4726601</a> |