

Inspection Photos
Location Name: Gray 31-16
Location ID: 332796



Crude oil tank placards on 1/25/19



Crude oil tank placards on 2/6/19

Inspection Photos
Location Name: Gray 31-16
Location ID: 332796



Produced water vault placards on 1/25/19



Produced water vault placards on 2/6/19

Inspection Photos
Location Name: Gray 31-16
Location ID: 332796



Crude oil tank placards on 2/6/19

